


2 IN. TOP MOUNT VALVE

REPLACEMENT PARTS



CALIFORNIA PROPOSITION 65 WARNING
 ⚠️ **WARNING:** Cancer and Reproductive Harm.
 ⚠️ **AVERTISSEMENT:** Peut Causer le Cancer et des Dommages au Système Reproducteur.
 ⚠️ **ADVERTENCIA:** Cáncer y Daño Reproductivo.
 www.p65warnings.ca.gov. P/N263085

Item	Part No.	Description
6 POSITION TOP MOUNT CLAMP-ON MULTI-PORT VALVE		
1	190059Z	Pressure Gauge
2	270210Z	Valve Body
3	272541	Valve Body O-Ring
4	272556Z	Sight Glass
5	272557Z	Drain Plug
6	272558Z	Handle
7	272567Z	Sight Glass Gasket
8	272568Z	Valve Top Assembly*
9	272573Z	Drain Plug O-Ring
10	272576Z	Valve Position Label
11	272590Z	Union Kit
12	274402Z	Diffuser

* Item #8 does not include screws.