


AUTOMATIC FEEDER - MODEL 300, 302, 300-19, 300-29

REPLACEMENT PARTS



Item	Qty.	Part No.	Description
Order No.:		R171016	R171026
Model No.:		300	302
Description:		AUTOMATIC FEEDER	SPA HOT TUB FEEDER

1	1	R172008W	3 in. threaded cap, white
2	1	R172009Z	O-ring, cap
3	Opt.	R172020	Check valve Old Style
5	1	R172023Z	3/8 in. o.d. x 1/4 in. i.d. tubing, 8 ft.
9	2	R172032Z	Tube fitting with compression nut
10	2	R172033Z	Gasket
11	2	R172034Z	Saddle clamp
14	1	R172037	Spa chamber #302 only
17	Opt.	R172052	Cap wrench
18	1	R172060Z	Control valve 1/4 in. NPT x tube with compression nut
19	1	R172036Z	Silicone lubricant, 3/4 oz.
20	1	R172061Z	Combination check valve / elbow
21	Opt.	R172080Z	Flow indicator w/check valve
23	Opt.	R172288	1-1/2 in.-2 in. Corrosion resistant check valve
24	Opt.	R172323	1/4 in. Corrosion resistant check valve
25		R172061ZB	Standpipe adapter, Bromine
26		R18761	6 in. Standpipe 3/8 in. o.d. x 1/4 in. i.d.
27	1	R18706Z	Compression nut only

Order No.: R172064

Parts bag for 300, 302, 300-19 & 300-29

9	2	R172032Z	Tube fitting with compression nut
10	2	R172033Z	Gasket
11	2	R172034Z	Saddle clamp
18	1	R172060Z	Control valve 1/4 in. NPT x tube with compression nut
19	1	R172036Z	Silicone lubricant
20	1	R172061Z	Combination check valve / elbow

CALIFORNIA PROPOSITION 65 WARNING
 ⚠️ **WARNING:** Cancer and Reproductive Harm.
 ⚠️ **AVERTISSEMENT:** Peut Causer le Cancer et des Dommages au Système Reproducteur.
 ⚠️ **ADVERTENCIA:** Cáncer y Daño Reproductivo.
www.p65warnings.ca.gov P8-2017-14